CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Corner originally established by John Å. Hurlburt under GLO contract number 201, dated August 5, 1873. Surveyor General record states:

Set fir post 4 ft. long 3 in. thick 2 ft. in ground for 4 sec cor

Fir 20 in dia N76°E 38 lks Pine 24 in dia 851°W 71 lks

Corner found by dated June 16, found by Herman D. Graden on GLO contract number 452, June 16, 1882. Surveyor General record states:

The 4 cor a post with 2 bearing trees



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Found no evidence of the original corner or it's accessories.

See Union County Survey Number 25-89

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 29 inches in the ground, from which;


New Bearing Trees; A 7 inch diameter Western Larch bears N63°E, 40.95 feet marked X BT A 9 inch diameter Western Larch bears N40°W, 28.74 feet marked 첫 834 BT

Painted a 6 inch red band around all BTs and attached Bearing Tree and Land Survey Monument signs.

Set a steel fencepost approximately 5 feet North with Land Survey Monument sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on September 30, 1989.

Witnesses: Rick Robinson and Jeff Petersen





I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the BT blaze.

Office of	County of	
	reby certify that the within instrume	
for record on the day of	UNION COUNTY	
(COUNTY OFFICIAL)		PUTY)
Form R6-7100-57 (9/71)	Date Received //- /4-89	

1-21

 $Z \sim 1.5$

*GPO-591-971, 1988