
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not originally established.



No record of subsequent monumentation found in Union County survey records DESCRIPTION OF CORNER EVIDENCE FOUND:

Not applicable.

See Union County Survey Number 1993-020.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At the position determined by survey I set a 2-1/2" X 30" aluminum pipe with aluminum cap marked as shown, 23 inches in the ground, from which;

A 18 inch diameter Ponderosa Pine bears S47°E, 198.4 feet, marked X BT A 17 inch diameter Ponderosa Pine bears N17°W, 108.87 feet, marked CN 1/16 S6 BT

Raised mound of stone 3 foot base to top cap.

Set a steel fence post approximately 3 feet north.

I hereby certify that the above corner point was perpetuated as hereon described on May 30, 1993.



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY TO THE
BUANE I GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Data Received 6-22-93

Data Filed 6-30-93

By P. ROBINSON DEPUTY

File No. 011-1993 R

B-03