


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not originally established.



DIAGRAM

No record of subsequent monumentation found in Union County survey records
DESCRIPTION OF CORNER EVIDENCE FOUND:

Not applicable.

See Union County Survey Number 1993-020.


DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey I set a 2-1/2" X 30" aluminum pipe with aluminum cap marked as shown, 24 inches in the ground, from which;

- A 31 inch diameter Ponderosa Pine bears N33°E, 105.5 feet marked NE BT
- A 26 inch diameter Ponderosa Pine bears N65°E, 107.08 feet marked C 1/4 S6 BT
- A 5/8 X 30" rebar with plastic cap, bears West, 5.90 feet marked BGA SURVEY MARKER
- A 20 inch diameter Ponderosa Pine bears N12°W, 222.0 feet marked NW BT

Set a steel fence post approximately 6 feet west.

I hereby certify that the above corner point was perpetuated as hereon described on May 30, 1993.



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
JULY 21 1984
DUANE I. GRIFFITH
644

UNION COUNTY SURVEYOR

Data Received 6-22-93

Date Filed 6-30-93

By R. ROBINSON, DEPUTY

File No. 01A-1993R

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.