


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not originally established.



No record of subsequent monumentation found in Union County survey records
DESCRIPTION OF CORNER EVIDENCE FOUND:

Not applicable.

**UNION COUNTY
SURVEYOR**

Date Received 6-22-93

Date Filed 6-30-93

By R. ROBINSON, DEPUTY

File No. 018-1993R

See Union County Survey Number 1993-020.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey I set a 2-1/2" X 30" aluminum pipe with aluminum cap marked as shown, 20 inches in the ground, from which;

A 1-1/2" Steel fence post bears West, 6.30 feet, with BGA bearing tree tag.

A 13 inch Ponderosa Pine bears N23°W, 215.00 feet marked E1/16 S6 BT


Raised mound of stone 4 foot base to top cap.

Set a steel fence post approximately 6 feet west.

I hereby certify that the above corner point was perpetuated as hereon described on June 3, 1993.

Witness:

Travis Foster



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.