CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: None.

DIAGRAM T3S R37E Z4					
		 	31		
		—— !		 	
				<u> </u>	


DESCRIPTION OF CORNER EVIDENCE FOUND: None.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proper position computed per the 1973 Manual of instructions I set a 1" \times 24" iron rebar with a 2" aluminum cap flush with the surface of the ground. The cap was stamped as shown below.

I marked two bearing trees. Each bearing tree has a copper nail with a 1 1/8" head stamped WTS and 56295LS driven between the letters B & T. Measurements were taken to the dent in the head of the nail with a Trimble 5601 electronic total station. Bearings are based on the survey control for County Survey No. 032-2004.

A 10" Ponderosa Pine bears N28°50'31"E, 114.85', scribed E1/16 S31 BT. An 11" Pondersa Pine bears N72°30'00"E, 35.03', scribed E1/16 S31 BT



I hereby certify that the above corner point was established as hereon described on August 27, 2004.

Witness: Kyle Lathrop David Haddock

REGISTERED PROFESSIONAL LAND SURVEYOR an X. Wallock OREGON JULY 9, 2001 STEPHEN K. HADDOCK 56295LS RENEWAL DATE 6-30-05

> **UNION COUNTY** SURVEYOR 151 8/04 Date Receive File No.