

UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

- Survey No. 11-65 position only
- Survey No. 12-65 position only
- Survey No. 25-66 position only
- Survey No. 27-69 position only
- Survey No. 76-74 found peg at corner
- Survey No. 93-74 found peg at corner
- Survey No. 101-74 found peg at corner

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Union County Survey Number 002-2014



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

No new corner monument was set, I set the following references in the curbs along McAlister Road referencing the corner position described above and used on Union County Survey Number 002-2014


NEW BEARING OBJECTS:

- A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears North 27°58'45" East, a distance of 42.23 feet,
- A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears South 33°36'07" East, a distance of 36.01 feet,
- A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears South 27°58'45" West, a distance of 35.46 feet,
- A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears North 33°36'07" West, a distance of 30.10 feet,

I hereby certify that the corner was referenced on March 21, 2014.

Witness: Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2014

**UNION COUNTY
SURVEYOR**

Date Received 3/24/14

Date Filed 3/24/14

Filed By [Signature]

File Number 007-2014R

I used a Leica GS 15 GPS unit in the establishment of the new accessories. The basis of bearing is the same as Survey No. 002-2014. Distances are to the center of the brass screw.