
## UNION COUNTY SURVEYOR

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Survey No. 4-69 position only Survey No. 39-69 position only Survey No. 56-71 position only Survey No. 65-73 position only Survey No. 67-73 position only Survey No. 008-2008 position only-Set 5/8" Iron Pin North 88°38'55" West, 33.76 feet DESCRIPTION OF CORNER EVIDENCE FOUND: **NONE** 



HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Survey No. 20-67 position only

Survey No. 21-67 position only

Found 5/8" Iron Pin set by survey number 008-2008 North 88°38'55" West, 33.76 feet

See Union County Survey Number 002-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

No new corner monument was set, I set the following references in the curbs along McAlister Road referencing the corner position described above and used on Union County Survey Number 002-2014

## **NEW BEARING OBJECTS:**

A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears North 45°54'08" East, a distance of 20.37 feet,

A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears South 41°46'33" East, a distance of 21.88 feet,

A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears South 45°54'08" West, a distance of 30.65 feet,

A brass screw and brass washer marked "OPLS 2219" in a lead plug in curb bears North 41°46'33" West, a distance of 32.95 feet,

I hereby certify that the corner was referenced on March 21, 2014.

Witness: Jeff Hsu

REGISTERED **PROFESSIONAL** LAND SURVEYOR ORÉGON RICK G. ROBINSON 2219

Renewal Date: December 31, 2014

UNION COUNTY **SURVEYOR** 

I used a Leica GS 15 GPS unit in the establishment of the new accessories. The basis of bearing is the same as Survey No. 002-2014. Distances are to the the brass screw.

C-15