

Index File No. 2-TT A-17

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T. 2S R. 40E

R.D. Union County Union

Merid. Will

N.F. W-W State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Steel post (regular fence rod type post). Post sits in mound of stone which mound appears to be original. This mound is about 2 1/2 chns East and visible from log road, and about 15 chns South of first switch back. Section lines to the south and west are plainly visible from here. The mound

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

appears to be a professional model.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estob. By _____
Agency _____

Signature _____

Title Surveyor (Contractor) Division _____ Headquarters _____

Date 6/25/80 FS-7100-52 (3/68)

| | |
|-------------------------------|--|
| UNION COUNTY SURVEYOR | |
| Date Received _____ | |
| Date Filed <u>12-18-87</u> | |
| By <u>G. LANGLITZ, DEPUTY</u> | |
| File No. <u>218-87R</u> | |

A-17

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Z-17


History of original corner establishment:

Corner established by Timothy W. Davenport under GLO contract No. 102, dated July 20, 1863.

Surveyor General records state:

Set post corner to Secs. 2, 3, 34 & 35, made mound of rock.

Corner visited by W.B. Barr during his survey of the east 2 miles of township line between T2 & 3 S, R 40 E, W.M., performed under GLO Contract No. 355 dated June 14, 1880, and his record states: "Intersect 160 lks south of corner to Secs. 2, 3, 34 & 35. Corner agreeing with description furnished by the Surveyor General. Post in mound of rock.



Description of corner evidence found:

Found original rock mound with steel fence post in mound.

UNION COUNTY SURVEYOR

Date Received 6-8-89

Date Filed 6-9-89

By G. LANGRISH, DEPUTY

File No. 121-89 R

Description of monument and accessories established to perpetuate the original location of this corner:

In center of rock mound...

Set 2½" aluminum cap on 2" x 30" aluminum pipe 20" in ground to bedrock & surrounded with mound of earth & stone. Set 6' fence post alongside corner with sign 54-9 attached. Cap marked as shown in corner diagram.

There being no trees available I marked bearing objects:

- A basalt boulder 22"x16" projecting 14" out of ground marked "BXO" brs N75½° E, 20.4' dist to X.
- A basalt boulder 32"x18" projecting 15" out of ground marked "BXO" brs S38° E, 38.8' dist to X.
- A basalt boulder 28"x19" projecting 12" out of ground marked "BXO" brs S17½° W, 14.5' dist to X.
- A basalt boulder 48"x24" projecting 22" out of ground marked "BXO" brs N42° W, 5.9' dist to X.

New bearing objects are painted with red paint.

Compass declination 20° East.

I hereby certify that the above corner monument was properly remonumented to U.S.F.S. standards by me on September 22, 1988, and witnessed by Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of..... County Surveyor..... County of..... Union.....
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)