


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

NONE

T 3 S R 40 E H-20



DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey No. 016-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position established by Survey No. 016-2013, I set a 5/8" X 30" iron pin with a 2 1/2" aluminum cap, marked as shown below, 29" in the ground, from which:

A 10" Ponderosa Pine bears North 56° East, a distance of 98.10 feet, marked SE 1/16 S 11 BT.

A 14" Ponderosa Pine bears North 70° West, a distance of 4.20 feet, marked SE 1/16 S 11 BT.

I set a steel fence post approximately 1 ft. East of monument.


I hereby certify that the corner was monumented on April 3, 2013.

Witness: Rick G. Robinson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2013



**UNION COUNTY
SURVEYOR**

Date Received 4/4/13

Date Filed 4/4/13

Filed By *[Signature]*

File Number 403-2013R

I used a magnetic compass and steel tape in the establishment of the bearing trees. Magnetic declination used was 16° East. The distances are to a 60d spike in the right hand side of the tree. Bearings are to a brass washer marked OPLS 83571 in the upper portion of the BT blaze.