CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by David T. Thompson under G.L.O. Contract Number 103, dated September 3, 1863. Surveyor General Record states: Set post for corner to Secs. 14, 15, 22, 23, in mound of earth with charred stake, pits, trench as per instructions.

Survey Numbers 69-71, 15-72, 49-72, 10-73, 11-73, 104-73, 51-74 38-75, 39-75, and 47-75 by James G. Voelz calls finding a

marked stone at the corner.

Survey number 64-78 by Duane I. Griffith, found a 1-inch diameter pipe which was harmonious with calls from previously mentioned surveys. This pipe was used for the section corner by Survey Numbers 64-78, 153-78, 40-79, 5-80 and 11-84.

Survey 15-84 by Victor McLind calls finding the pipe disturbed and using the stone as

Survey 31-84 by Anderson-Perry & Associates calls the pipe found on its side and using the stone as the corner.

Description of corner evidence found:

Found stone with "X" chiseled in top. Buried 18" below road surface.

Found disturbed 1"x12" iron pipe on side above stone.


Description of monument and accessories I established to perpetuate the original location of this corner:

In place of stone, I set a 2 1/2-inch x 30-inch galvanized iron pipe with attached brass cap marked as shown 36" in ground, top being 6" below road surface. I buried the stone south and along side the brass capped monument.

Fence Corner 25 feet East

Fence Corner 26 feet South

Corner set 7-5-84 Witness: Ray Crapo



10 to Received 7-18-84

Inte Filed 7-20-84

By G. LANGLITZ, DEPUTY

FIE No. 929-84R



T3S

S15

S22⁻

R40E

S14

S23

1984 PLS 1099

GARY L. LANGLITZ

Office of	County of
	rtify that the within instrument was filed in this effice
for record on the day of	
***************************************	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO---798-276

N-17	
DIAGRAM	
T3S	R40E
S15	S14
S22	S23
r pipe whi	ch was har-

RENEWAL

NUMENT SET (PROCEDURE AN		MONUMENT DETAIL

		·
ACCESSORIES TO ALLES		_
ABOVE THE STANE WHEN T	SEVERAL KAILROAD SE	PIKES AND THE FOUND PI
ABOVE THE STONE WHEN I	COVERED IT, TO AT	TRACT A METAL DETECTOR
CH OF MONUMENT, ACCESSOR	IES AND GENERAL AREA	LOCATION & COMMENTS
CH OF MONUMENT, ACCESSORI	IES AND GENERAL AREA	LOCATION & COMMENTS
CH OF MONUMENT, ACCESSORI	IES AND GENERAL AREA	LOCATION & COMMENTS
CH OF MONUMENT, ACCESSORI NEEDED FOR CLARIFICATIO	IES AND GENERAL AREA	LOCATION & COMMENTS
CH OF MONUMENT, ACCESSORINEEDED FOR CLARIFICATIO	IES AND GENERAL AREA	LOCATION & COMMENTS
NEEDED FOR CLARIFICATIO	IES AND GENERAL AREA	LOCATION & COMMENTS
NEEDED FOR CLARIFICATIO	IES AND GENERAL AREADN)	LOCATION & COMMENTS
CH OF MONUMENT, ACCESSORINEEDED FOR CLARIFICATIO	LES AND GENERAL AREA	LOCATION & COMMENTS
NEEDED FOR CLARIFICATIO	IES AND GENERAL AREA	LOCATION & COMMENTS
NEEDED FOR CLARIFICATIO	IES AND GENERAL AREA	LOCATION & COMMENTS
NEEDED FOR CLARIFICATIO	IES AND GENERAL AREA	LOCATION & COMMENTS
NEEDED FOR CLARIFICATIO	ON)	COMPASS DECLIN
NEEDED FOR CLARIFICATIO	RIVEWRY	COMPASS DECLIN
NEEDED FOR CLARIFICATIO	ON)	COMPASS DECLIN FIRM/AGENCY PARTY CHIEF
COUNTY D	ON)	COMPASS DECLIN
COUNTY D	ON)	COMPASS DECLIN FIRM/AGENCY_ PARTY CHIEF_ WITNESSES
COUNTY D	ON)	COMPASS DECLIN FIRM/AGENCY PARTY CHIEF
COUNTY D	RIVEWAY	COMPASS DECLIN
COUNTY D	UNION COUNTY SURVEYOR	COMPASS DECLIN
COUNTY	UNION COUNTY	COMPASS DECLIN
COUNTY D	UNION COUNTY SURVEYOR	COMPASS DECLIN
COUNTY D	UNION COUNTY SURVEYOR Data Raceived 4-24-84	COMPASS DECLIN

File No. <u>854-84 R</u>

PAGE 2 OF 2

SOURCE RESTORATION FORM	CORNER NUMBER
TOWNSHIP 35 , RANGE 40 E, SECTION(S) 1415, 22, 23	<u>N-17</u>
COUNTY UNION STATE OREGON DATE 3-27-84	UNION COUNTY SURVEYOR
CORNER DESIGNATION	JORVETOR
SECTION CORNER	Date Received 4 - 24 - 84
1	Date Filed 4-26-84
S15 S. 14 S.22 S.23	By G. LANGLITZ DEPUTY
522 523	File No. 854-84 R
REFERENCES TO PRIOR RECORDS SURVEY No. 46-79	REFER TO SURVEY NO. 15-84 CONDITION REPORT ONLY NOT FOUND RENEWED SURVEYED IN THIS SPACE RESERVED FOR
MONUMENT(S) FOUND: (CONDITION AND SOURCE)	USE OF COUNTY SURVEYOR
LARGE STONE WITH "X" SCRIBED IN TOP. BURIED 18" BELOW POAD SURFACE. I DID NOT DIG UP STONE TO MEASURE SIZE. ABOVE THE STONE AND ABOUT 1" BELOW SURFACE I FOUND A 1"X 12" IRON PIPE WHICH APPEARED TO HAVE BEEN DISTURBED. THE STONE IS SHOWN AND USED FOR CONTROL IN SURVEY NO. 46-79. THE PIPE IS SHOWN AND USED FOR CONTROL IN SURVEY NO. 64-78.	MONUMENT DETAIL
ACCESSORIES FOUND: (CONDITION AND SOURCE) .	
None.	

History of original corner establishment:

Corner originally established by David T. Thompson under GLO contract number 103, dated September 3, 1863. Surveyor General record states: Set post for corner to Secs 14, 15, 22 & 23 in mound of earth with charred stake, pits, trench as per instructions.

Survey numbers 69-71, 15-72, 49-72, 10-73, 11-73, 104-73, 51-74, 38-75, 39-75, and 47-75 by James G. Voelz calls finding a marked stone at the corner.

DIAGRAI	V.
T3\$	R40E
S 15	s 14
S 22	\$ 23

Survey number 64-78 by Duane I. Griffith, found a 1 inch diameter pipe which was harmonious with calls from the previously mentioned surveys. This pipe was used for the Section corner by survey numbers 64-78, 153-78, 40-79, and 5-80.

Description of corner evidence found:

Found 1 inch diameter pipe as per survey number 64-78

UNION COUNTY SURVEYOR	
Date Received 2 April 84	
Date Filed 3 April 84	
By H. Tenny B 835 File No. 258-84 R	

Description of monument and accessories I established to perpetuate the original location of this corner:

NONE

See survey number 7-84

REGISTERED PROFESSIONAL LAND SURVEYOR	
Lugon T. Black	_
OREGON JULY 13, 1973 GREGORY T. BLACKMAN 991	

Office of	. County of
State of, I hereby certify the	
for record on the day of	
by	***************************************
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

HORIZONTAL CONTROL DATA

UNION COUNTY, OREGON OREGON STATE PLANE, NORTH ZONE (3601)

STA. NAME: 9336

CORNER COMMON TO: 14,15,22 & 23 GEODETIC COOR: NAD 83(91)

TWP.3 S. RGE.40 E. LAT: 45°17'48.60135" N

DATE SET: OCT. 1993 LONG: 117°47'16.19256" W

SURVEYOR: WALTER L. CASWELL SP. COOR: NAD 83(91)

PLS 737

PORTLAND, OR. 97229

N: 606026.393 INT.FT.

FIRM: EAGLE GPS SURVEY CORP 13545 NW SCIENCE PARK DR E: 8899859.031 INT.FT.

(503) 643-1073 THETA: 1°55'24.355"

TYPE: GPS SCALE FACTOR: 0.999897075

ORDER: SECOND CLASS: 1 ELEV: 3184.41 US.FT.

ELEV. DATUM: NGVD 29

************************ DIRECTIONS "TO REACH": FROM HIGHWAY 237 AND HAEFER LANE IN COVE, GO EAST ON HAEFER LANE FOR ABOUT A MILE, UNTIL HAEFER LANE TURNS AND GOES TO THE NORTH. A GRAVEL ROAD TAKES OFF HERE, AND CONTINUES EAST, AND ALONG WITH THIS ROAD THERE IS ANOTHER SMALL SECTION OF GRAVEL ROAD WHICH EXTENDS THE OTHER CENTERLINE OF HAEFER LANE TO FORM A SORT OF TURNAROUND. THE

CORNER IS IN THE GRAVEL, VERY NEAR THE POINT WHERE THE CENTERLINES OF HAEFER LANE WOULD MEET. THE CORNER IS A 5/8" IRON ROD WITH A 2 1/2" ALUMINUM CAP.

> fasull Mu OREGON JULY 8, 1966 WALTER L CASWELL

737

REGISTERED **PROFESSIONAL**

AND SURVEYOR

EXPIRES 12/31/95

1 METER = 3.2808333333333... U.S. FEET = 39.37 INCHES 1 METER = 3.280839895 INT'L FEET OR 1 INCH = 2.54 CM. TO CALCULATE ELEVATION FACTOR (IN THE NORTH AMERICAN CONTINENT) DIVIDE 20,906,000 BY (20,906,000 + ELLIPSOID ELEV. IN FEET) SHEET 34 OF 37