


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Minor Partition Plat Number 1998-20

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

The true position of the Center-West 1/16th corner falls in a pond, at a point North 0°08'30" East, a distance of 10.00 feet from the true corner position, I set a 5/8" x 30" iron pin with 2" aluminum cap marked as shown below, 28" in the ground, for a witness corner from which:

NEW BEARING OBJECTS:


A 5/8" x 30" iron pin with a 1½" aluminum cap marked BGB SURVEY MARKER NORTH RP bears North 7°17' East, a distance of 15.75 feet, from the witness corner monument. (North 4°30'29" East, a distance of 25.70 from the TRUE 1/16th corner position)

A 5/8" x 30" iron pin with a 1½" aluminum cap marked BGB SURVEY MARKER EAST RP bears South 77°03' East, a distance of 43.06 feet, from the witness corner monument. (South 89°31' East, a distance of 41.99 from the TRUE 1/16th corner position)

I hereby certify that the corner was monumented on July 2, 1998.
Witnesses: Greg Blackman, Jr. and Jeff Madsen

REGISTERED
PROFESSIONAL
LAND SURVEYOR,
Rick G. Robinson
OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 1998



**UNION COUNTY
SURVEYOR**

Date Received 7/20/98
Date Filed 7/29/98
Filed By Jeff T. Dahn
File Number 010-1998R

I used a total station instrument in the establishment of new accessories. The basis of bearing is the same as that of the stated partition plat. The distance to the bearing object is to a punch mark in the center of the cap.