

GOVERNMENT CORNER RESTORATION FORM

TOWNSHIP 35, RANGE 40 E, SECTION(S) 22, 23

COUNTY UNION STATE OREGON DATE 3-27-84

CORNER DESIGNATION

$\frac{1}{4}$  522 | 523

REFERENCES TO PRIOR RECORDS ORIG. G.L.O. SURVEY,  
SURVEY No. 46-79

MONUMENT(S) FOUND: (CONDITION AND SOURCE)

NONE

I SEARCHED FOR THIS CORNER BUT FOUND NO  
EVIDENCE.

ACCESSORIES FOUND: (CONDITION AND SOURCE)

NONE

CORNER NUMBER

P-17

**UNION COUNTY  
SURVEYOR**

Date Received 4-24-84

Date Filed 4-26-84

By G. LANGLITZ, DEPUTY

File No. 853-84R

REFER TO SURVEY NO. 15-84

CONDITION REPORT ONLY

NOT FOUND

RENEWED

SURVEYED IN

THIS SPACE RESERVED FOR  
USE OF COUNTY SURVEYOR

MONUMENT DETAIL

RENEWAL

MONUMENT SET (PROCEDURE AND DESCRIPTION)

MONUMENT DETAIL

I DID NOT SET THIS CORNER.  
IT FALLS IN A CHERRY ORCHARD ABOUT  
20' EASTERLY OF AN IRRIGATION DITCH.  
I CALCULATED THE POSITION OF THIS CORNER  
BY PROPORTION FROM THE SECTION CORNERS 1/2 MILE  
NORTH AND 1/2 MILE SOUTH, IN ORDER TO LOCATE  
THE CORNERS OF A 50 ACRE TRACT BELONGING  
TO REUBEN S. TESKE. I SET A 1/2" STEEL RE-BAR  
330.00 FT. NORTHERLY FROM THIS CORNER ON THE  
SECTION LINE, AS A PROPERTY CORNER

NEW ACCESSORIES

SKETCH OF MONUMENT, ACCESSORIES AND GENERAL AREA  
(IF NEEDED FOR CLARIFICATION)

LOCATION & COMMENTS

COMPASS DECLIN. \_\_\_\_\_  
 FIRM/AGENCY \_\_\_\_\_  
 PARTY CHIEF \_\_\_\_\_  
 WITNESSES \_\_\_\_\_

SURVEYOR'S SEAL

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Victor M. Mc Lind*

OREGON  
 JULY 17, 1970  
 VICTOR M. MCLIND  
 934

**UNION COUNTY  
 SURVEYOR**

Date Received 4-24-84

Date Filed \_\_\_\_\_

By G. LANGUITZ, DEPUTY

File No. 853-84 R