CERTIFIED RECORD OF LAND CORNER MONUMENTATION

David T. Thompson, under government contract number 103.

Surveyor General notes state;

"Set post for 4 section corner from which;"

A pine, 12 inches in diameter bears \$ 30 W, 34 links dist.

A pine 24 inches in diameter bears \$ 3 E 500 links dist.

Solution 14 Section Corner from which;

No.subsequent record of remonumentation in survey records.

Description of corner evidence found:

Found SW. bearing tree stump, decayed, and lower blaze visible.

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 1½ × 36" gaivanized pipe, with brass cap

marked as shown, at the called bearing and distance from the 1.W. T35 R40E S.W. bearing tree, from which New BT'S.

A fir, 18 inches in deameter, bears S 75 E, 29.2 feet, marked 4 S 24 BT.

I used a steel tape and a magnetic compass with 20 degree East declination set into compass.

See survey number 46-79

REGISTERED
PROFESSIONAL
LAND SURVEYOR

JULY 13, 1973
GREGORY I. BLACKMAN

1979

S 24

State of, I hereby certif	y that the within instrument was filed in this office	100.110.1
for record on the day of		OMICH COUNTY
(COUNTY OFFICIAL)		SURVEYOR
TOOK TO PPICIAL!	(DEPUTY)	A/
		Date Received 4-19-8
		Date Filed 4-19-84
		BY G. LANGLITZ DEPO
R6-7100-57 (9/71)		File No 844 - 94 D

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established under GLO contract number 103 executed by Daniel P. Thompson, dated September 3rd 1863. Surveyor General field notes state: Set post for 1/4 sec corner from which:

A Pine 12 in diam bears South 30° West, 34 lks dist.

A Pine 24 in diam bears South 3° East, 500 lks dist.

In Survey Number 46-79, Gregory T. Blackman monuments the corner from original GLO evidence.
Union County monumentation records states:
Set a 1 1/4" x 36" galvanized pipe, with brass cap marked as shown, at the called bearing and distances from the S.W. bearing tree, from which New BT'S A fir, 18 inches in diameter, bears South 75° East, 29.2 feet, marked 1/4 S

24 BT. A pine, 20 inches in diameter, bears North 84° West, 9.2 feet, marked 1/4 S 23 BT.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 1 1/4" iron pipe with a 2 1/2" brass cap, 6" above ground, from which:

A 20" diam. Fir stump, 2' tall, bears South 75° East, a distance of 29.20 ft., with BT scribe visible.

A 27" diam. Pine stump 18" tall bears North 84° West, a distance of 9.20 ft., with BT scribe visible.

SEE SURVEY NUMBER 030-2024

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the iron pipe monument:

NEW BEARING OBJECTS:

A 22" Ponderosa Pine bears North 62° East, a distance of 12.60 ft., marked 1/4 S24 BT A 11" Ponderosa Pine bears South 22° West, a distance of 21.45 ft., marked 1/4 S23 BT A 10" Douglas Fir bears South 57° West, a distance of 18.45 ft., marked 1/4 S23 BT A 4" Douglas Fir bears North 2° West, a distance of 18.00 ft., marked X BT

No trees available in the SE quadrant.

I hereby certify that the corner was perpetuated on June 11th, 2024.

Witnesses: Kyle Tucker, Adam Gordon

T3S R40E 1/4 S23 S24 1979 PLS 991

T3S R40 EP-21

S

23

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2025

UNION COUNTY
SURVEYOR

Date Received 8/19/24

Date Filed 8/19/24

Filed By 24/29/24

Filed Number 041-2024R

I use a tape and compass in the establishment of the new bearing objects. 14° East was used for declination and measured to a brass washer labeled "OPLS 83571" in the BT blaze at the base of the tree. Distances are to a 60D nail in the right side of the base of the center of the tree.