
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 027-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 12" in the ground, with mound of stone around monument, 2 ft. base to top of cap, from which:

NEW BEARING TREES:

A 27" Ponderosa Pine bears N $25^{\circ}E$, a distance of 40.28 ft, marked SW 1/16 S24 BT.

A 28" Ponderosa Pine bears N $74^{\circ}W$, a distance of 34.68 ft, marked S24 X BT.

I hereby certify that the corner was monumented on August 18, 1997. Witnesses: Jeff Madsen and Greg Blackman Jr.

PROFESSIONAL
LAND SURVEYOR

GREGORY T. BLACKMAN 991

OREGON

Renowal Date: December, 31 1997

BGI	В	
T3S R	T3S R40E	
SW 1/16		
S 24	ļ	
1997		
OPLS	991	

UNION COUNTY SURVEYOR

Date Received 8.23-97

Date Filed 8-23-97

Filed By R. ROBINSON, DETUTY

File Number 020-1997R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the bearing tree blaze.