
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 027-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, with ring of stone around monument, from which:

NEW BEARING TREES:

A 16" Ponderosa Pine bears N 58°E , a distance of 23.75 ft, marked CS 1/16 S24 BT.

A 18" Ponderosa Pine bears N 73°W, a distance of 38.56 ft, marked CS 1/16 S24 BT.


I hereby certify that the corner was monumented on August 18, 1997. Witnesses: Jeff Madsen and Greg Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1973

GREGORY T. BLACKMAN
991

Renewal Date: December, 31 1997



UNION COUNTY SURVEYOR

Date Received 8-23-97

Date Filed 8-23-97

Filed By R ROBINSON DEAUTY

File Number <u>022-1997</u> R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the bearing tree blaze.