CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.

T3S R40E T-23 S 25

No record of monumentation found in UNION COUNTY survey records. DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 027-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 26" in the ground, with ring of stone around monument, from which:

NEW BEARING TREES:

- A 11" Douglas Fir bears N 61°E, a distance of 10.15 ft, marked C\ S25 BT.
 A 20" Ponderosa Pine bears S 10°E, a distance of 35.83 ft, marked C\ S25 BT.
 A 11" Douglas Fir bears S 44°W, a distance of 22.66 ft, marked C\ BT.
 A 12" Ponderosa Pine bears N 53°W, a distance of 1.75 ft, marked C\ BT.

I hereby certify that the corner was monumented on August 13, 1997. Witnesses: Jeff Petersen, Jeff Madsen and Greg Blackman Jr.

REGISTERED **PROFESSIONAL** LAND SURVEYOR BC. OREGON GREGORY T. BLACKMAN 991 Renowal Date: December, 31 1997

T3S R40E C 1/4 S 25 1997 **OPLS** 991

UNION COUNTY SURVEYOR

Date Received 8-23-97

Date Filed 8-23-97

Filed By R. Rossinson, Dorry

File Number 025-1997R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the bearing tree blaze.

T-23