
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.

DESCRIPTION OF CORNER EVIDENCE FOUND:

See Survey Number 034-2001.



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2  $\frac{1}{2}$ " x 30" aluminum monument marked as shown below, 26" in the ground, from which:

NEW BEARING TREES:

A 14 inch diameter Western Larch bears N 16°E, a distance of 21.75 ft., marked E 1/16 S26 BT.

A 11 inch diameter Douglas Fir bears S  $37^{\circ}E$ , a distance of 48.14 ft., marked E 1/16 S35 BT.

I hereby certify that the corner was monumented on October 9, 2001. Witnesses: Norb Volny and Greg Blackman Jr.


REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON

2219

Renewal Date December 31, 2002



UNION COUNTY
SURVEYOR

Date Received /0/23/01

Pate Received ....

Date Filed 10 /23/01

File Number <u>039-</u> 2001 R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2219 to the bearing tree blaze.