


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 003-2015

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 2 1/2" x 30" aluminum pipe, 30" in the ground, with a 2 1/2" aluminum cap, marked as shown below, from which:

A 5/8" x 30" iron pin bears North 1°00' East, a distance of 20.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER N RP.

A 5/8" x 30" iron pin bears East, a distance of 20.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER E RP.

A 5/8" x 30" iron pin bears South 1°00' West, a distance of 20.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER S RP.

A 5/8" x 30" iron pin bears East, a distance of 20.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER E RP.


Set a steel fence post approximately 1 foot East of corner monument.
I hereby certify that the corner was monumented on January 26, 2015

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015



BAGGETT - GRIFFITH & BLACKMAN

T3S R40E

C 1/4 S 31

2015

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 1/29/15

Date Filed 1/29/15

Filed By N. G. G. G.

File Number 001-2015R

I used a Leica GS-15 RTK GPS in the establishment of the accessories. Bearings and distances are to the center of the aluminum caps. Basis of bearings is as per Survey Number 003-2015.