
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by David P. Thompson GLO contract number 103, dated September 3, 1863. Surveyor General record states:

Set post for West 1/4 corner in mound of earth, with charred stake, pits, trench as per instructions.



DESCRIPTION OF CORNER EVIDENCE FOUND:

No evidence found

See Survey Number 034-2001.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum monument marked as shown below, 26" in the ground, from which:

NEW BEARING TREE and OBJECTS:

A 7 inch diameter Ponderosa Pine bears N 31°E , a distance of 52.93 ft, marked 1/4 S35 BT.

A $5/8" \times 30"$ iron pin with aluminum cap marked BGB SURVEY MARKER S35 RP, bears South 33° East a distance of 6.61 feet.

A 5/8" x 30" iron pin with aluminum cap marked BGB SURVEY MARKER S34 RP, bears South 12° East a distance of 9.78 feet.

A 5/8" x 30" iron pin with aluminum cap marked BGB SURVEY MARKER NW RP, bears North 13° West a distance of 9.23 feet.

Raised a small mound of stone around monument.


I hereby certify that the corner was monumented on October 8, 2001. Witnesses: Norb Volny and Greg Blackman Jr.


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1988

RICK G. ROBINSON
2219

Renewal Date December 31, 2002





I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to the center of the aluminum caps and a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2219 to the bearing tree blaze.