
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Survey Number 024-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At a position determined by survey, I set a 5/8" x 30" iron rod with a 2 ½" aluminum cap marked as shown below, 30" in the ground. From which:

NEW BEARING OBJECTS:

A 8" White Fir bears North 55° East, a distance of 3.95 feet, marked CS 1/16 S35 BT. A 9" White Fir bears North 24° West, a distance of 14.40 feet, marked CS 1/16 S35 BT.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on April 24, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

T3S R40E C S35 C 2015 OPLS 83571

UNION COUNTY SURVEYOR

Date Received 4/28/

tuén DA -

File Number 095-2015R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.