
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

#### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

### DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Survey Number 024-2015

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At a position determined by survey, I set a 5/8" x 15" iron rod with a 2  $\[mu]$ " aluminum cap marked as shown below, 15" in the ground, with a collar of stone 4 foot diameter. From which:

## **NEW BEARING OBJECTS:**

A 9" Ponderosa Pine bears North 66° East, a distance of 45.40 feet, marked S 1/16 S36 BT. A 9" Ponderosa Pine bears North 29° West, a distance of 17.20 feet, marked S 1/16 S35 BT.

I set a steel fencepost approximately 2 foot West of corner monument.

I hereby certify that the corner was monumented on April 23, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

SEPFREY S. HSU
83571

Renewal Date: June 30, 2017

T3S R40E S1/16
S35 S36

2015

OPLS 83571

UNION COUNTY
SURVEYOR

Date Received 4/27/15

Date Filed By 4/27/15

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.