CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Alonzo Gesner under GLO contract No. 683 and dated June 7, 1898.

Surveyor General records state: Set fir post 4' long 4" square 24" in ground for Cor to Secs 5,6,31 & 32 4" square 24" in ground for Cor to Secs 5,6,31 & 32 mkd T2SS32 on the NE,R41ES5 on SE, T3SS6 on SW, S31 on NW with 5 notches on E & 1 notch on W edges from which:
A fir 10" diam brs N5°E, 26 lks mkd T2SR41ES32 BT.
A spruce 12" diam brs S34°E,19 lks mkd T3SR41ES5 BT.
A fir 9" diam brs S41°W, 26 lks mkd T2SR41ES6 BT.
A fir 7" diam brs N26°30'W,18 lks mkd T3SR41ES31 BT.

A 8-5		
DIAGRAM		
Т 2	S	R 41 E
S	31	S 32
S	б	S 5
т 3 ['] s 1987		
ORLS 1639		

Description of corner evidence found:

No trace of original wood post.

A spruce 18" dia brs $S34^{\circ}E$, 12.5' dist with healed blaze. A fir stub 15" dia & 12' high brs $S41^{\circ}W$, 17.2' dist with fragmentery scribes on partially healed blaze. A fir windblow 9" dia & root hole brs $N23^{\circ}W$, 11.0'(record, $N26\frac{1}{2}^{\circ}W$, 18 lks) with full scribes on open blaze. A rotten root stub brs $N03^{\circ}E$, 16.0'(record, $N05^{\circ}E$, 26 lks).

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by distance intersection from sections 5 & 6 standing BTs.....

Set $2\frac{1}{2}$ " aluminum cap on 2" aluminum pipe 25" in ground with 5" projecting out of ground with surrounding rock mound and 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established: Alpine fir 9" dia brs N23°E, 10.2' dist mkd T2SR41ES32 BT. Alpine fir 10" dia brs S87 $\frac{1}{2}$ °W, 16.3' dist mkd T3SR41ES6 BT. Alpine fir 7" dia brs N67°W, 12.5' dist mkd T2SR41ES31 BT.

Each BT has a sign 54-3 and signs 54-4 or 54-9 attached below a 6" band of red paint, and each new BT has a brass washer marked PLS 1639 nailed flush with BT blaze.

Compass declination 190 East.

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on July 17, 1987 In Ochastus

REGISTERED PROFESSIONAL LAND SURVEYOR William L. Hanley

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

Office of	County Surveyor	County of Union		
State of	Oregon , I hereby c	ertify that the within instrument was filed in this office		
for record on the day of				
by				
(COUNTY OFFICIAL)		(DEPUTY)		

(DEPUTY)

Data Received 8-12-87

S

UNION COUNTY SURVEYOR

Form R6-7100-57 (9/71)