

DOCUMENT DESCRIBE NEW

ACCESSORIES DESCR

Work Done By—  
Certified Cor. R

Index FI

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*Whitman* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 35 R. 41E VI Mer.

Section 17 Corner common to Sections  
15, 16, 21, and 22

DESCRIPTION OF CORNER

Corner consists of a Stone

Dimension above ground 6X8X10 inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE
		≡	≡				

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>735</u> <u>N41E</u> <u>515</u>	<u>735</u> <u>R41E</u> <u>521</u>	<u>735</u> <u>R41E</u> <u>516</u>	
<u>BT</u>	<u>BT</u>	<u>BT</u>	

Species: W.F. W.F. LP

Diameter: 2 1/2" 12 1/4" 14 1/4"

Bearing: N20E N40E N72 1/2 W

Distance: 834E 334E 196

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Signature. \_\_\_\_\_

Date. \_\_\_\_\_ Title. \_\_\_\_\_ 8-3027

N-13

**UNION COUNTY SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 276-87R

N-13