
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established




No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established.

See map of survey dated August, 1988.



Description of monument and accessories I established to perpetuate the

original location of this corner: At the position determined by survey, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

New BTs: A 24 inch diameter Spruce bears S17°E, 16.07 feet marked W1/16 S30 BT A 24 inch diameter White Fir bears N36°W, 34.79 feet marked W1/16 S19 BT


Raised a mound of stone around monument, 3 ft. base to top of cap.

Painted a 6 inch red band around all BTs and attached 54-3 and 54-9 signs.

Set a steel fencepost approximately 5 feet North with 54-9 and 54-2 signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on August 8, 1988.

Witness: Greg Blackman





I used a steel tape and magnetic compass in the establishment of new accessories. I used 18° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of County of	
State of , I hereby certify that the within instrument was filed in this office	
for record on the day of	, 19
by	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276