
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner not established in original survey.



Description of corner evidence found:

NONE



See map of survey number 30-86 filed in the office of the Union County Surveyor Description of monument and accessories l'established to perpetuate the original location of this corner:

At the position determined by survey, I set a  $2^{1/2} \times 30^{11}$  aluminum pipe with aluminum cap marked as shown, 28 inches in the ground: from which:


An 18 inch Spruce bears N 15° E, 7.41 feet, marked X BT.

A 22 inch Douglas Fir bears N  $30^{\rm O}$  W, 42.21 feet, marked N 1/16 S30 BT.

Set a steel fence post approximately 5 feet West with a 54-9 sign attached.

Corner set : 9/16/86

Witness: Greg Blackman, Rick Robinson



Brass washer marked OPLS 644 nailed to BT Blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d Spikeset in right side of tree when facing tree, unless otherwise stated.

PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964

DUANE I. GRIFFITH

REGISTERED

Form R6-7100-57 (9/71)

\$U.8. GOVERNMENT PRINTING OFFICE - 1983-793-276

11-14