


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:
NONE

UNION COUNTY SURVEYOR

Date Received 10-20-86
 Date Filed 10-27-86
 By G. LANGLITZ, DEPUTY
 File No. 243-86R


See map of survey number 30-86 filed in the office of the Union County Surveyor
 Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground and raised a small mound of stone around cap, from which:

An 8 inch Tamarack bears N 68° E, 48.36 feet, marked 1/16 S 30 BT.

A 16 inch Tamarack bears S 28° W, 64.12 feet, marked 1/16 S 31 BT.

Set a steel fence post approximately 5 feet East with a 54-9 sign attached.

Corner set : 9/9/86
 Witness: Greg Blackman, Rick Robinson



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....
 State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

II-2