


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 3 S R 41 E Y-01



DESCRIPTION OF CORNER EVIDENCE FOUND:

None found.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE
ORIGINAL LOCATION OF THIS CORNER:**

At position by survey I set a 5/8" x 30" iron pin, 26" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears North 44° East, a dist. of 23.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER.


A 12" Western Larch bears South 87° East, a dist. of 40.70 feet, marked Lot 10 S31 BT.

Set steel fence post approx. 0.5 ft. East


North/South bearing fence line falls approx. 3 ft. East

I hereby certify that the corner was monumented December 3, 2025

Witness: Kyle Tucker



I use a tape and compass in the establishment of the new bearing tree. Bearings are measured from the center of the aluminum cap to a brass washer marked "OPLS 83571" tacked to the BT blaze. Declination used was 14° East. Distances are measured from the center of the aluminum cap to a 60D spike in the center right base of the tree or the center of the aluminum cap.



Y-01