
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner not previously established




No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

NONE

See map of survey dated July, 1988.



Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2%" x 30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, from which:

New BTs:

An 11 inch diameter Western Larch bears N 16°E, 16.95 feet marked X BT. A 13 inch diameter Western Larch bears N 54°W, 31.40 feet marked SW 1/16 , S 31 BT.


Corner falls in the remains of an old North South fence line.

Painted a 6 inch red band around all BTs and attached bearing tree tags and 54-9 signs on back.

I hereby certify that the above corner point was perpetuated as hereon described on July 6, 1988.

Witnesses: Greg Blackman, Jeff Petersen





I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked

State of....... , I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... ..... by ...... (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

GPO---798-276