
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established




No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

NONE

See map of survey dated July, 1988.



Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, and raised a small mound of stone from which:

New BTs:


A 9 inch diameter Spruce bears S 8°E, 17.43 feet marked SE 1/16 S31 B.T. A 15 inch diameter Spruce bears N 41°W, 45.53 feet marked X B.T.

Painted a 6 inch red band around all BTs and attached bearing tree tags and 54-9 signs on back.

I hereby certify that the above corner point was perpetuated as hereon described on July 6, 1988.

Witnesses: Greg Blackman, Jeff Petersen





I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked wAPLS 991 to the BT blaze

Form R6-7100-57 (9/71)

GPO-798-276