


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX: J 23

History of original corner establishment:



A. Corner established by US Deputy Surveyor Frank W. Campbell working under contract numbered 498, dated March 10, 1884.

Surveyor General's Record states:

Set a fir post 3 ft long 3 ins sqr 24 ins in ground for 1/4 sec cor marked 1/4S on N face; from which

a spruce 10 ins dia brs S42E 51 lks dist marked 1/4S RT
a spruce 24 ins dia brs N84W 42 lks dist marked 1/4S RT

Description of corner evidence found:

B. MONUMENT FOUND:


none

ACCESSORIES FOUND:

nothing found after several diligent searches and opening of one large spruce with what appears as healed blaze, but nothing found. Area has not been logged, but down woody material heavily deteriorated due to wet site.

Description of monument and accessories established to perpetuate the original location of this corner:

C. I set a 2.5 inch dia. by 30 inch long aluminum monument 27 inches in the ground at the single proportionate position. No stones available. I mark the cap:



NEW ACCESSORIES ESTABLISHED with magnetic declination of 20 deg. East

33" spruce bears S34W at 21.8 ft scribed " 1/4 S13 RT"
19" spruce bears N42E at 26.9 ft scribed " 1/4 S12 BT"

Painted red band around each bearing tree
Placed brass washer with "PLS 2060" at base of each new RT blaze
Placed USDA Forest Service metal signs 54-3 (RT) and 54-9 (LSM) on each bearing tree. Placed 54-4 (ATTENTION) sign on tree near corner.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

UNION COUNTY SURVEYOR	
Date Received	<u>10-2-89</u>
Date Filed	<u>10-11-89</u>
By	<u>G. LANGRISH</u>
File No.	<u>193-89 R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>Edwin A. Stryker</i>
OREGON JULY 15, 1983 EDWIN A. STRYKER 2060