

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Corner established in 1884 by Frank W. Campbell under General Land Office contract number 498. Surveyor General record states:

Set a Basalt stone 13"x10"x9", 9 inches in the ground for 1/4 section corner, marked 1/4 on the west face.

From which:

A spruce 36" in diameter bears S 80° W, 15 lks. distant, marked 1/4 S BT.

A spruce 36" in diameter bears S 39° E, 55 lks. distant, marked 1/4 S BT.



No record of subsequent monumentation found in County Records. Description of corner evidence found:

NONE

See map of survey dated July 1985, filed with Union County Surveyor. Description of monument and accessories established to perpetuate the


original location of this corner: At proportionate position I set a 2 1/2 x 30" aluminum pipe with aluminum cap marked as shown 26" in ground.

From which:

An 8" White Fir bears N 23° E, 26.1 feet, marked 1/4 S 15, BT on a single blaze.

An 8" White Fir bears S 56° W, 24.9 feet, marked 1/4 S 16, BT. on a single blaze.

I placed a steel fence post with a 54-2 and 54-4 sign 5 feet North and I place a steel fence post with a 54-2 sign 5 feet South.



Corner set July 8, 1985
Witness: Rick Robinson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gregory T. Blackman

OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Brass washer nailed to BT blaze.
Used steel tape and magnetic compass
with 20° East declination.
Measured to center of new B.T.s

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY
SURVEYOR

Date Received 8-23-85

Date Filed 8-7-85

By G. LANGUITZ, DEPUTY

File No. 46-85 R