


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX: T, 23

History of original corner establishment:

A. Corner not established by CLO



Description of corner evidence found:

B. MONUMENT FOUND:

none

Description of monument and accessories I established to perpetuate the original location of this corner:

C. As the locus of corner falls within a live healthy tree I mark it as the corner. Said corner tree is a 27 inch dbh white fir I scribe the north face "C 1/4 S13" and place a brass washer marked "PLS 2060" at base of the blaze. I place a 54-9 (LSM) sign on the north and south faces of the tree and place a 54-2 (PROPERTY BOUNDARY) sign on the east face. Note that the locus of said corner does not fall in the center of this tree, but within the northeasterly perimeter.

NEW ACCESSORIES ESTABLISHED with magnetic declination of 20 deg. East

12" douglas fir bears N12W at 13.7 ft scribed "C 1/4 S13 BT"
15" white fir bears S44E at 25.9 ft scribed "C 1/4 S13 BT"
Set a 2.5 inch dia by 30 inch long aluminum monument 27 inches in the ground as a reference monument. No stones available. I mark the cap:
The true corner bears S76-16'-23"W at 2.18 feet T4N R39E WM
from the reference monument. 1/4

S13 ← P.M.
2.18
1989

Painted red band around corner tree and around each bearing tree. Placed brass washer with "PLS 2060" at base of each new BT blaze. STRYKER PLS 2060
Placed USDA Forest Service metal signs 54-3 (BT) and 54-9 (LSM) on each bearing tree. Placed 54-4 (ATTENTION) and 54-2 (PROPERTY BOUNDARY) signs on steel fence posts east and south of corner tree.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

UNION COUNTY	
SURVEYOR (DUTY)	
Date Received	<u>10-2-89</u>
Date Filed	<u>10-11-89</u>
By	<u>G. LANGLITZ</u>
File No.	<u>195-89R</u>

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Edwin A. Stryker

OREGON
JULY 15, 1983
EDWIN A. STRYKER
2060