

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1884 by Frank W. Campbell under General Land Office contract number 498.


Surveyor General record states:

" A spruce 8 inches in diameter which I marked 1/4 S on North face for 1/4 section corner.

From which:

A spruce 10 inches in diameter bears S 10°E, 8 lks. dist, marked 1/4 S BT

A spruce 10 inches in diameter bears N 40°W, 38 lks dist, marked 1/4 S BT.



No record of subsequent monumentation found in County Records. Description of corner evidence found:

NONE

See map of survey dated July 1985, filed with Union County Surveyor. Description of monument and accessories established to perpetuate the

original location of this corner: At proportionate position I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 28" in the ground.

From which:


An 8 inch Larch bears N 65° E, 9.9 feet, marked 1/4 S 16 BT on a single blaze.

A 12" Larch bears S 12° W, 9.1 feet, marked 1/4 S 21 BT on a single blaze.

I set a steel fence post 5 feet East, with a 54-2 and 54-4 sign attached. I also set a steel fence post 5 feet West with a 54-2 sign attached.

Corner set July 8, 1985

Witness: Rick Robinson
Ray Crapo, Stratton French



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gregory T. Blackman

OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to center of new B.T.s

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received ^{☆ GPO-798-276} 7-23-85

Date Filed 8-7-85

By G. LANGLITZ, DEPUTY

File No. 47-85 R