## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original Survey was by Frank W. Campbell under G.L.O. Contract No. 507, dated June 28, 1884.

Set basalt stone 16 x 11 x 7 inches, 12 inches in ground for corner to Sections 7, 8, 17 & 18. Marked with four notches on south and five notches on east edges.

F	ile	Index	No.	<u>J-5</u>
	ı	DIAGRAI	V	
		T4N	R40E	
		S7	\$8	
		S18	S17	

## From which:

A fir 10 inches diam. bears  $N51^{0}E$ , 25 lks. dist., marked T4N R40E S8 BT. A fir 8 inches diam. bears  $S41^{0}E$ , 14 lks. dist., marked T4N R40E S17 BT. A fir 12 inches diam. bears  $S50^{0}W$ , 80 lks. dist., marked T4N R40E S18 BT. A fir 6 inches diam. bears  $N10^{0}W$ , 22 lks. dist., marked T4N R40E S7 BT.

Description of corner evidence found:

Found 14 x 11 x 7 stone firmly set in ground clearly marked four notches on south side and five notches on east side.

Found old bearing tree bearing N52<sup>O</sup>E, 18.0 ft. from stone with visible blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

T4N R40E W.M.

At corner position set  $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set pipe 24" in ground with mound of stone to cap.

<b>S7</b>	<b>S8</b>
S18 OR PLS	S17
1978	

From which:

A fir 12" in dia. bears N23 $^{\rm O}$ W, 88.2 ft., scribed T4N R40E S7 BT. A fir 18" in dia. bears S68 $^{\rm O}$ E, 6.5 ft., scribed T4N R40E S17 BT. A fir 16" in dia. bears S88 $^{\rm O}$ W, 43.0 ft., scribed T4N R40E S18 BT. A fir 24" in dia. bears N25 $^{\rm O}$ E, 28.6 ft., scribed T4N R40E S8 BT.

Painted blazes red and 6" red band around BT's. Placed 54-3's and 54-4's on old BT and new BT's. Placed brass washer stamped PLS 1051 on foot blaze of new BT's. Placed 54-4 sign on metal fence post 4' north of corner. Placed 54-5 sign on tree on north side of forest service road No. N50 1000 ft. south of corner.

PROFESSIONAL LAND SURVEYOR

Bores

OREGON
OCT. 17, 1975

REGISTERED

BARRY B. BAREOUR 1 0 5 1 I hereby certify that the above corner monument was re-established as herein described.

Witnesses: Rodger Orton Glen Wagoner

Jeff Anderson

June 20, 1978

UNION COUNTY SURVEYOR

Date Filed
Ву

Date Received

Office of County Surveyor County of Union File No.

State of Oregon I hereby certify that the within instrument was filed in this office for record on the day of 1978

(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

∜ GPO 799-509