CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.

DIAGRAM TAN RAOE NW16+518

Description of corner evidence found:

No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a $2\frac{1}{2}$ " x 30" iron pipe 26" in the ground with a brass cap marked as shown:

From which I scribed BI's:

A Tamarack $14\frac{1}{2}$ " in dia. bears N $60^{0}30$ 'W a distance of 32.40'. A Fir $9\frac{1}{2}$ " in dia. bears S $17^{0}30$ 'E a distance of 12.80'.

I nailed a brass washer marked PLS 933 to the BT blazes.


I set a steel fence post 5° East and South with signs 54-9 and 54-2 on them.

I painted a red band around the BT's and face of scribe and nailed 54-3 and 54-9 signs to them.

I used a steel tape and a magnetic compass with a $19^{0}30$ ' East variation and measured a horizontal distance to the center of BT's with a steel chain.

This corner was set July 28, 1983

Witness by: W. Keith Sands Brent Reynolds



PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 17, 1970
DAVID H. KRUMBEIN
933

Office of County Surveyor	County of Union	
State of Oregon , I hereby certify the	t the within instrument was filed in this office	
for record on the day of by	, 19	UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	POUNTAGE
20 7100 07 (2 (24)		

Form R6-7100-57 (9/71)

SEE SURVEYS -37-83
-38-83
Ry G. LANG.
File No. 353

Date Removedee.276 9-26-83

Date Filed 9-28-83

By G. LANGLITZ DEPUTY

File No. 353-83 R