


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.



Description of corner evidence found:

No evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

At the position described above, I set a 2 1/2" x 30" iron pipe 26" in the ground, with a brass cap marked as shown:

From which I scribed BT's:


A Tamarack 8" in dia. bears S 33° E a distance of 9.80'.
A Fir 10" in dia. bears S 50° W a distance of 3.90'.

I nailed a brass washer marked PLS 933 to the BT blazes.
I set a steel fence post 5' East and West with signs 54-9 & 54-2.
I painted a red band around the BT's and face of scribe, and nailed signs 54-3 & 54-9 to them.

I used a steel tape and a magnetic compass with a 19° 30' East variation and measured a horizontal distance to the center of BT's with a steel chain.

This corner was set July 29, 1983

Witness by: W. Keith Sands
Brent Reynolds



REGISTERED PROFESSIONAL LAND SURVEYOR

David H. Krumbain

OREGON
JULY 17, 1970
DAVID H. KRUMBAIN
933

Office of..... County Surveyor..... County of..... Union.....
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE SURVEYS - 37-83
- 38-83

UNION COUNTY SURVEYOR
Date Received 9-26-83
Date Filed 9-28-83
By G. LANGLITZ, DEPUTY
File No. 356-83 R