Index File No. =

History of original corner establishment:

Corner established by Frank W. Campbell under G.L.O. Contract #507 in August, 1884. Surveyor's General's notes state: "Set a post 3 ft. long 3 ins. dia. 24 ins. in ground for 1/4 Sec. corner marked 1/4 S. on W. face, from which: A Fir 4 ins. dia. brs. S.66 E. 23lks dist. marked 1/4 S.B.T.. A Spruce 20 ins. in dia. brs. N.74 W. 65lks dist. marked 1/4 S.B.T.." 1/4 S.B.T.."

DIAGRAM	
T4N	
R39E R40E	i I
1/4	
S13 + S18	
1	

Description of corner evidence found:

No evidence of original corner could be found. A dillisearch was made before the survey and after the corner A dilligent position was determined.

Location tag was found and a couple of trees were opened, but no visible scribing.

Corner falls in small opening near timber corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

At single proportionate measurements from found corners, set $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set pipe 25" in the ground.

No rock in the area.

T4N R39E R40E OR PLS 1051 1978

File No. 26-83 R

From which: A Fir 22" in dia. bears S35°E, 36.0 feet, scribed 1/4S18BT. A Fir 12" in dia. bears N84°W, 67.1 feet, scribed 1/4S13BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-4 on steel fence post 3' East of corner. Placed 54-5 on tree 15' North of corner.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON OCT. 17, 1975 BARRY B. BARBOUR 1051

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers Dan T. Rowland

October 27, 1978

		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Date Received ⇔ GPO 799-509
		Date Filed