CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established by Frank Campbell under GLO contract no. 507 in 1884.

Set a Fir post 3 feet long 3 ins. square 24 inches in ground mkd ½ S on W face.

A Spruce 10" dia. bears N 70°E 56 1ks A Spruce 24" dia. bears S 50°W 33 lks DIAGRAM TAN RADE

Description of corner evidence found:

Nothing was found during either preliminary reconnaissance or after corner location was established by proportionment.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the proportioned location we set:

A $2\frac{1}{2}$ " Brass Cap on a $2\frac{1}{2}$ " x 30" galvanized iron pipe 26" in the ground mkd as shown:

From which:

A Tamarack 13" in dia. bears N $62^{\circ}E$ a dist. of 16.5 feet A Fir 11.5" in dia. bears N $75^{\circ}W$ a distance of 20.55 ft.

BT's have red painted blazes and a 6" band around them, with signs 54-3 and 54-9 nailed to them. A Brass Washer mkd PLS 933 was nailed to lower scribe

Set a steel fence post 5° North with signs 54-4 and 54-9

I used a steel tape and megnetic compass with a 19030' East variation and measured the horizontal distance to the center of the tree with a steel tape.

July 28, 1983

By: W. Keith Sands Witness: Brent Reynolds REGISTERED OREGON

Date Filed 9-28-83

TAN RAOÈ

933

Office of Surveyor	County of Union	933
State of Oregon , I hereby certi	ify that the within instrument was filed in thi	s office
for record on the day of	by UNION COUNTY SUZYEYOZ	
(COUNTY OFFICIAL)	(DEPUTY)	20% AELOW
6-7100-57 (9/71)		9-26-83

Form R6-7100-57 (9/71)

SEE SURVEUS-37-83