## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.

DIAGRA	am		
T4 N	RO 40E		
546	c + c	518	

Description of corner evidence found:

No evidence found.

## Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a  $2\frac{1}{2}$ " x 30" iron pipe 26 inches in the ground with a Brass Cap marked as shown:

From which I scribed B.T.'s:

A Spruce 10.5" in diam. bears N  $30^{\circ}$ E a distance of 11.25 feet. A Spruce 17" in diam. bears S  $84^{\circ}$ W a distance of 43.70 feet.

I nailed a brass washer marked PLS 933 to the B.T. blazes.

I set a steel fence post 5' East and West with signs 54-4, 54-9 & 54-2. I painted a red band around B.T.'s and face of scribe, and nailed 54-3 & 54-9 signs.

I used a steel tape and a magnetic compass with  $19^{
m o}30\,{}^{\prime}$  East variation and measured a horizontal distance to the center of B.T.'s.

July 21, 1983

By: W. Keith Sands Witness: Brent Reynolds

REGISTERED PROFESSIONAL

R40E 1983

State of...... Oregon ......... I hereby certify that the within instrument was filed in this office

......by ....... (COUNTY OFFICIAL)

(DEPUTY)

JMBEIN

Form R6-7100-57 (9/71)

SEE SURVEYS

UNION COUNTY SURVEYOR

Date Received 9-26-83

Date Filed 9-28-83