CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided Section.

DIAGRAM TAN RAOE

SE 16 . 518

Description of corner evidence found: No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a $2\frac{1}{2}$ " x 30" iron pipe 26 inches in the ground, with a Brass Cap marked as shown:

From which I scribed B.T.'s:

A Fir 26" in diam. bears N $10^{0}30$ 'W a distance of 59.50 feet. A Fir 21" in diam. bears S $80^{0}30$ 'W a distance of 74.0 feet.

I nailed a brass washer marked PLS 933 to the B.T. blazes. I set a steel fence post 5' North and West with signs 54-4, 54-9, and 54-2. I painted a red band around the B.T.'s and face of scribe, nailed 54-3 & 54-9.

I used a steel tape and a magnetic compass with 19⁰30' East variation and measured a horizontal distance to the center of B.I.'s.

This corner was set July 21, 1983

Witness by: W. Keith Sands Brent Reynolds PROFESSIONAL LAND SURVEYOR

OREGON JULY 17, 1970 DAVID H. KRUMBEIN 933 TAN RADE SE YIL . 518 1983 PLS 933

(COUNTY OFFICIAL)

(DEPUTY)

38-83

Form R6-7100-57 (9/71)

SEE SURVEYS 37-83

Date Regained 9-26-83

Date Filed 9-28-83

By G. LANGLITZ, DEPUTY

File No. 371-83 R

UNION COUNTY SURVEYOR