CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishmen	History	of original	corner	establishment:
---	---------	-------------	--------	----------------

None.

Index File No. 0-18	
DIAGRAM	
T4N R40E NW 1/16 S23	

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set corner 24" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E:

A 16" Pine bears N57°E., 22.1 ft., scribed NW1/16S23 BT. A 12" Fir bears N60°W., 69.5 ft., scribed NW1/16S23 BT. Painted blazes red and 6" red band around.

Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 and 54-9 on steel fence post 5° south and 54-2 on steel fence post 5' west of the corner.

Corner falls about 150 ft. south of main road.

T4N R40E NW | 1/16 S23 OR PLS 1051 1981

50-83 R

File No.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> OREGON OCT. 17, 1975 BARRY B. BARBOUR

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland Beverly Weaselhead

June 16, 1981

Office ofCounty .Surveyor	 e
FOWARD L PERRY by COUNTY OFFICIAL)	UNION COUNTY - SURVEYOR
Form R6-7100-57 (9/71)	Date Received
	Date Filed