CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.

DIAGRAM
TAN RAOE
C/4 - 519

Description of corner evidence found:

No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a $2\frac{1}{2}$ " x 30" iron pipe 26" in the ground with a brass cap marked as shown:

From which I scribed BT's:

A Spruce 12" in diameter bears N $25^{0}\mathrm{W}$ a distance of 91.30 ft. A Fir 14" in diameter bears N $36^{0}\mathrm{E}$ a distance of 54.25 ft.

I nailed a brass washer marked PLS 933 to the BT blazes.


I set a steel fence post 5' North and South with signs 54-4, 54-9, & 54-2.

I painted a red band around BT's and face of scribe and nailed signs 54-9 and 54-3.

I used a steel tape and a magnetic compass with East variation and measured a horizontal distance to the center of BI's.

July 21, 1983

By: W. Keith Sands Witness: Brent Reynolds



CAVID H. KRUMBEIN

registered PROFESSIONAL

Office of County Surveyor	County of Union
State of	
for record on the day of , 19	
by	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

SEE SURVEYS - 37-83 - 38-83

Union County Surveyor

Date & *** 9-26-83

Date Filed 9-28-83

By G. LANGLITZ, DEPUM

File No. 362-83 R