


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.




Description of corner evidence found:

No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a 2 1/2" x 30" iron pipe 16" in the ground with a rock mound to the top of cap, with a brass cap marked as shown:



From which I scribed BT:

A Tamarack 24" in dia. bears S 73°E a dist. of 287.40 ft.  
 No other trees within 300' of corner.  
 Fences line in West 26.6 feet running North and South.  
 A 5/8" x 30" Iron Rod with an aluminum cap marked "B.O." bears N 25°W 64.95 feet set steel post 1° South. Pin is in fence line.  
 I nailed a brass washer marked PLS 933 to the BT blaze.  
 I set a steel fence post 5' North and South with signs 54-4, 54-9 & 54-2.  
 I painted a red band around B.T.'s and face of scribe, and nailed on signs 54-9 & 54-3.  
 I used a steel tape and a magnetic compass with 19°30' East variation and measured a horizontal distance to the center of B.T.'s.

July 21, 1983  
 By: W. Keith Sands  
 Witness: Brent Reynolds

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*David H. Krumbain*  
 OREGON  
 JULY 17, 1970  
 DAVID H. KRUMBAIN  
 933

Office of..... Surveyor..... County of..... Union.....  
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY  
 SURVEYOR

---

Date Received 9-26-83  
 Date Filed 9-28-83  
 By G. LANGLITZ, DEPUTY  
 File No 361-83 R