


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. p-18

History of original corner establishment:

None.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground alongside pine stump. No rock in area.

From which by magnetic declination of N20°E:

A 20" Tamarac bears N51°E., 61.3 ft. scribed CWL/16S23 BT.

A 18" Tamarac bears S25°E., 56.8 ft. scribed CWL/16S23 BT.

Painted blazes red and 6" red band around.

Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs.

Placed 54-2 and 54-9 on steel fence post 5' south of the corner and 54-2 on steel fence post 5' north of the corner.

T4N R40E  
W1/16

C —+— C

S23  
OR PLS 1051  
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland  
Beverly Weaselhead

June 16, 1981



*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of... County Surveyor..... County of... Union.....  
State of... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the 24 day of... August....., 1981.  
HOWARD L. PERRY..... by Harry J. Langlit  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received 8-27-81

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 54-83 R