


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Q-18

History of original corner establishment:

None.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. No rock in area.

From which by magnetic declination of N20°E:

A 20" Tamarac bears S80°E., 7.0 ft., scribed SW 1/16 S23 BT.

A 20" Tamarac bears S89°W., 59.5 ft., scribed SW 1/16 S23 BT.

Painted blazes red and 6" red band around.

Placed 54-3s and brass washers stamped PLS 1051 on BTs.

Placed 54-2 and 54-9 on steel fence post 5' south and

54-2 on steel fence post 5' north of the corner.

T4N R40E
SW 1/16



S23
OR PLS 1051
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland
Beverly Weaselhead

June 16, 1981

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of... County Surveyor..... County of... Union.....
State of... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the... 24... day of... August....., 1981
Howard L. Perry..... by *Gary J. Daugherty*
(COUNTY OFFICIAL)..... (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 8-27-81

Date Filed _____

By _____

File No. 57-83 R