CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not set.

Index File No. R-4

Description of corner evidence found:

None.

Corner is about 500' North of road #62, about 6' East of a North-South fence and 150' North of an East-West fence.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set $2\frac{1}{2}$ " x 30" galvanized pipe with brass cap marked: Set pipe 22" in the ground.

T4N R40E \$19 E \$30 1/16 OR PLS 1051 1978

No rock in the area.

From which: A Fir 28" in dia. bears N71°E, 39.5 feet, scribed E1/16S19BT. A Fir 14" in dia. bears S21°E, 33.0 feet, scribed E1/16S30BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 4' North and 54-2 and 54-9 on steel fence post 3' West of corner. Placed 54-5 on tree 5' East of corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OCT. 17. 1975
BARRY B. BARBOUR
1 0 5 1

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses:

David L. Landers
Dan T. Rowland

October 31, 1978

Office of County Surveyor County of Union
State of Oregon ... I hereby certify that the within instrument was filed in this office.

for record on the ... 20. day of ... November, 19.78

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

Date Received one Date Filed by ______ File No. 59-83 R .

URION COUNTY