


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

R-7

**History of original corner establishment:**

Corner established in 1884 by Frank W. Campbell, under General Land Office Contract No. 507.



**Surveyor General record states:**

Set a post 3 feet long 3" square 24" in ground for 1/4 section corner marked 1/4 S BT on N. face

**from which:**

- A spruce, 10" diam. bears N.33°E 19 links dist. marked 1/4 S BT
- A spruce, 30" diam. bears S.30°E. 27 links dist. marked 1/4 S BT.

**Description of corner evidence found:**

At assumed corner the post was not in evidence. I found 1 original BT:


A spruce, live with scribing visible, now 43" diam. in the S.E. Quadrant.

**Description of monument and accessories I established to perpetuate the**

original location of this corner As the evidence found agrees with the original GLO record, I reversed the bearing and distance of the BT found and set a 1" galvanized iron pipe 36" long with a 2 1/2" Brass Cap marked:

**From which (new BTs)**

- A spruce, 7" diam. bears S.65°E. 25.0 feet dist. marked 1/4 S BT
- A fir, 8" diam. bears S.72°W. 20.8 feet dist. marked 1/4 S BT



NOTE: I placed USFS bearing tree signs on the new BTs and a Brass Washer stamped ORLS 506 in the lower Blaze.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Ralph P. Thompson*

OREGON  
MAY 13, 1960  
RALPH P. THOMPSON  
506

Office of ..... County ..... Surveyor ..... County of ..... Union .....

State of Oregon ..... , I hereby certify that the within instrument was filed in this office

for record on the 27 day of June ..... 1973, at 9 o'clock A.M., (signed)

*James D. ...* by ..... (COUNTY OFFICIAL) ..... (DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 61-83 R