


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-10

History of original corner establishment:

Not set.



Description of corner evidence found:


Found 3" square post painted red near surveyed point.

Corner is 30' East of a track road.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 25" in the ground.

No rock in the area.

T4N R40E
S21
W  1/16
OR PLS 1051
1978

From which: A Tamarac 12" in dia. bears N02°E, 26.9 feet, scribed W1/16S21BT. A Tamarac 11" in dia. bears S84°E, 29.3 feet, scribed W1/16S28BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 4' South and 54-2 and 54-9 on steel fence post 5' East of corner. Placed 54-5 on tree 2' East of corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Dan T. Rowland

October 16, 1978

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of... County Surveyor County of... Union
State of... Oregon I hereby certify that the within instrument was filed in this office
for record on the... 20 day of... November , 1978

..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

**UNION COUNTY
SURVEYOR**

Date Received 10/16/78

Date Filed _____

By _____

File No. 64-83 R