

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-11

History of original corner establishment:

Corner established by Frank W. Campbell under G.L.O. contract number 507 dated June 28, 1884.

Surveyor General's records state:

A spruce 30" diameter which I marked for 1/4 sec corner 1/4 S on N face from which:

A spruce 18" dia bears N 33° W., 33 lks dist marked 1/4 S BT
A spruce 16" dia bears S 48° E., 31 lks dist marked 1/4 S BT

Description of corner evidence found:

NONE

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 2 1/2" brass cap on a 2" iron pipe 31" long 6" above the ground with a 6' steel fence post alongside with signs 54-4 and 54-2 attached.

New bearing trees:



A spruce 10" dia bears N 28° W., 9.75 ft dist marked 1/4 S 21 BT
A fir 11" dia bears S 22° E., 12.3 ft dist marked 1/4 S 22 BT

Each BT has a sign 54-3 attached 6" below a band of red paint and has a brass washer marked RPE 2808 nailed flush with BT blaze.

Brass cap is marked: T 1/4 N R 40 E

1/4 S 21
S 28

R P E 2 8 0 8
1976



Office of Surveyor County of Union
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 26 day of August, 1976

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY SURVEYOR
Date Received _____
Date Filed _____
By _____
File No. 66-83R