


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-13

History of original corner establishment:

Original survey was by Frank W. Campbell under G. L. O. contract No. 507, dated June 28, 1884.



Set a spruce post 4 ft. long, 4 ins. square, 24 ins. in the ground for corner to Secs. 21, 22, 27 and 28, from which:

- A spruce 27 ins. diam. bears N 13° E, 10 lks. dist., mkd. T 4 N R 40 E S 22 BT.
- A spruce 24 ins. diam. bears S 60° E, 10 lks. dist. mkd. T 4 N R 40 E S 27 BT.
- A spruce 10 ins. diam. bears S 21° W, 23 lks. dist. mkd. T 4 N R 40 E S 28 BT.
- A spruce 12 ins. diam. bears N 72° W, 35 lks. dist. mkd. T 4 N R 40 E S 21 BT.

Description of corner evidence found:

None conclusive. Piece of original BT scribing was nailed to a tree in the near vicinity, but was unable to identify the source.

Description of monument and accessories established to perpetuate the original location of this corner


Set a 2½-inch brass cap on 2-inch iron pipe, 31 ins. long, 6 ins. above the ground with a 6 ft. steel fence post alongside with sign 54-4 attached.

- 7 " fir bears N 21° E, 20.4 ft. dist., mkd. T 4 N R 40 E S 22 BT.
- 9" spruce bears S 70° E, 46.0 ft. dist., mkd. T 4 N R 40 E S 27 BT.
- 14" larch bears S 47° W, 59.0 ft. dist. mkd. T 4 N R 40 E S 28 BT.
- 10" spruce bears N 20° W, 55.8 ft. dist., mkd. T 4 N R 40 E S 21 BT.

BTs have sign 54-3 attached 6 inches below band of red paint and have a brass washer nailed flush with BT blaze. Washer is marked RPE 2808.

Monument marked:

T 4 N R 40 E	
S 21	S 22
S 28	S 27
RPE 2808	
1976	



Office of.....**Surveyor**..... County of.....**Union**.....
 State of.....**Oregon**....., I hereby certify that the within instrument was filed in this office
 for record on the 26 day of August, 1976.
 _____ by _____
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY	
SURVEYOR	
Date Received _____	
Date Filed _____	
By _____	
File No. <u>65-83R</u>	